

RESOLUTION NO. HDLC-5

A RESOLUTION OF THE HISTORIC DISTRICT AND LANDMARKS COMMISSION MODIFYING RESOLUTION NO. HDLC-3 RELATING TO THE MINIMUM PERFORMANCE CONDITIONS FOR THE CONSTRUCTION, REHABILITATION AND PRESERVATION OF RESIDENTIAL BUILDINGS AND STRUCTURES WITHIN THE HISTORIC DISTRICT OR UPON A LANDMARK OR LANDMARK SITE.

BE IT RESOLVED by the Historic District and Landmarks Commission, and pursuant to Yreka Municipal Code Section 17.04.058, as follows:

Subsection 8, Windows and Doors, of Section C of Resolution No. HDLC-3, is hereby modified to provide as follows:

"C. 8. Windows and Doors


"If aluminum is used, it shall not be mill finish or clear anodized. Window proportions must harmonize with the proportions of the building. Placement of unusual windows, such as round, stained glass or storm windows, should be considered carefully in terms of the exterior composition. Doors should be accompanied with exterior transition spaces such as porches, canopies, or landings. Flush doors are discouraged."

PASSED AND ADOPTED this 14th day of May, 1981, by the following vote:

AYES: Eddy, Langford, McDonald, Meamber, Tyrer

NOES: None

ABSENT: Favero


Vice Chairman

ATTEST:

Yreka City Clerk